



Description: Marking rings PC 40_

Lapp code: Lapp 61822820

The **Test voltage** of the cable Lapp 61822820 is /.

Application range

- For Single core marking
- Marking after assembly
- Also possible to use for marking wires before assembly

/

In our Cable list on next page you can find all interesting information acc. article Lapp 61822820 and much more.

CABLE LIST - all informations you need you can find here

| Product Name | Lapp Nr. | Article designation | Width x height (mm) | Sleeve length (mm) | Area of application Ø (mm) | Contents (unit) |
|---------------------|---------------|---------------------|---------------------|--------------------|-------------------------------|-----------------|
| PC 40 | | | | | | |
| Marking rings PC 40 | Lapp 61822400 | PC 40 / 0 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822410 | PC 40 / 1 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822420 | PC 40 / 2 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822430 | PC 40 / 3 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822440 | PC 40 / 4 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822450 | PC 40 / 5 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822460 | PC 40 / 6 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822470 | PC 40 / 7 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822480 | PC 40 / 8 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822490 | PC 40 / 9 | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822500 | PC 40/blank | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822510 | PC 40 / A | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822520 | PC 40 / B | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822530 | PC 40 / C | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822540 | PC 40 / D | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822550 | PC 40 / E | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822560 | PC 40 / F | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822570 | PC 40 / G | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822580 | PC 40 / H | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822590 | PC 40 / I | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822600 | PC 40 / J | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822610 | PC 40 / K | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822620 | PC 40 / L | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822630 | PC 40 / M | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822640 | PC 40 / N | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822650 | PC 40 / O | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822660 | PC 40 / P | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822670 | PC 40 / Q | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822680 | PC 40 / R | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822690 | PC 40 / S | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822700 | PC 40 / T | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822710 | PC 40 / U | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822720 | PC 40 / V | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822730 | PC 40 / W | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822740 | PC 40 / X | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822750 | PC 40 / Y | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822760 | PC 40 / Z | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |

Marking rings PC 40_

Lapp 61822820



| Product Name | Lapp Nr. | Article designation | Width x height (mm) | Sleeve length (mm) | Area of application Ø (mm) | Contents (unit) |
|---------------------|---------------|---------------------|---------------------|--------------------|-------------------------------|-----------------|
| Marking rings PC 40 | Lapp 61822770 | PC 40 // | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822780 | PC 40 / . | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822790 | PC 40 / , | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822800 | PC 40 / : | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822810 | PC 40 / = | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822820 | PC 40/earth | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822860 | PC 40 / + | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822870 | PC 40 / - | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |
| Marking rings PC 40 | Lapp 61822880 | PC 40 / ~ | 6,9 x 6,7 | 4 | 5 - 6,2 | 200 |